

Part No.	Code Number	Number of	Dimension of connector, PCB mounting pattern, metal mask, FPC, FFC, and shielded FFC										Dimension of drawing for packing							
Part No.		contacts	Α	В	С	D	Е	F	G	Н	J	K	L	М	Р	Q	R	S	U	V
FH63S-10S-0.5SH(99)	CL580-4414-0-99	10	12.7	4.5	5.55	4	2	7.15	9.9	3	7.1	5.5	9.1	4.9	24	_	11.5	14.1	29.4	25.4
FH63S-20S-0.5SH(99)	CL580-4419-0-99	20	17.7	9.5	6.55	9	1.5	12.15	14.9	6	12.1	10.5	14.1	9.9	32	28.4	14.2	19.1	37.4	33.4
FH63S-30S-0.5SH(99)	CL580-4415-0-99	30	22.7	14.5	5.55	14	2	17.15	19.9	8	17.1	15.5	19.1	14.9	44	40.4	20.2	24.1	49.4	45.4
FH63S-40S-0.5SH(99)	CL580-4416-0-99	40	27.7	19.5	10.55	19	1.5	22.15	24.9	11	22.1	20.5	24.1	19.9	44	40.4	20.2	29.1	49.4	45.4
FH63S-50S-0.5SH(99)		50	32.7	24.5	15.55	24	2	27.15	29.9	13	27.1	25.5	29.1	24.9	56	52.4	26.2	34.1	61.4	57.4
FH63S-60S-0.5SH(99)		60	37.7	29.5	20.55	29	1.5	32.15	34.9	16	32.1	30.5	34.1	29.9	56	52.4	26.2	39.1	61.4	57.4

*The products without code number are currently under planning.


Please contact HIROSE for detailed information about product variation.


<Dimension table>

]		DRAWING NO.	EDC-388109-99-00	
	H 25	PART NO.	FH63S-**S-0.5SHC9	9)
		CODE NO.	CL580	<u></u>
		7	0	

This connector requires delicate and careful handling. To prevent connector/FPC breakege and contact failure (mating failure, FPC pattern breakage, etc), read through the instructions shown below and handle the connector properly. This instruction manual is applicable to usage with FPC/FFC/shielded FFC. Example 4) Example 5) Example 6) [Connector part nomenclature] Signal contact Locking lever Top (pick-up surface) Locking lever close (Horizonal state) FPC insertion opening Ground contact Housing FPC(Slanted) <Top view:</pre> (Front view) |Operation and precautions| 1. Initial condition FPC(Slanted) The product is supplied with the locking lever closed. Locking lever does not have to be operated before inserting FPC. 3. FPC insertion check Make sure that the FPC tabs are located in proper position Do not open the locking lever when the FPC is not inserted. after FPC insertion (Example 7).
(The FPC position is to be aligned by the protrusion of the locking lever.) The locking lever is to be used only when extracting the FPC (Example 1).

- Do not insert FPC or operate locking lever before mounting (Example 1). [Caution] Do not insert the FPC at an angle and/or stop it before insertion is completed (Example 8.9).
 As this product is designed for one action locking, the locking lever does not have to be operated after inserting FPC. Example 1) - When deliverd -Example 8) Example 9) Locking lever open Locking lever close FPC is inserted in slanted angle and Insertion of FPC is shallow and Tabs of FPC are visible when FPC is not fully inserted to the end. not fully inserted to the end. completely inserted to the end End position of FPC End position of FPC <u>End position of F</u>PC Before mounting 2. How to insert FPC Insert the FPC into the connector opening horizontally to the PCB surface (Example 2). $\frac{1}{2}$ Insert it properly to the very end. [Caution] Make sure the locking lever is closed when inserting the FPC.
Do not insert the FPC when the locking lever is open (Example 3).
Do not insert the FPC when the locking lever is pressed from above a finger (Example 4). FPC - Align both sides of FPC horizotally to the sides of FPC(shallow) FPC(Slanted) the connector opening and insert straight forward. Insertion of FPC is shallow The line between FPC is inserted in slanted angle - Do not twist the FPC to up and down or right and left or an angle(Example 5.6). FPC and housing is and there is big clearance and there is a big clearance between FPC and housing. parallel each other between FPC and housing. Section — locking area -Section - locking area -Section - locking area -Example 2) Locking lever close Locking lever close Locking lever open (Horizonal state) Locking lever Locking lever run on the FPC. <Instruction manual(1)> EDC-388109-99-00 FH63S-**S-0.5SH(99) Align both sides of FPC horizotally to the sides of (Horizonal state) the connector opening and insert straightforward. $\sqrt{5/8}$ CL580 FORM HC0011-5-8 1






| Instructions for mounting on the PCB|

Follow the instructions shown below when mounting on the PCB.

[Caution]

- Refer to recommended layouts on the page 1 for PCB and stencil pattern Shorter pattern width than the recommended PCB dimension.
- could cause solder wicking and/or flux penetration.
- Larger pattern than the recommended stencil dimension, could cause solder wicking and/or flux penetration.
- Clearance underneath the contact lead and the housing is very small. In case solder resist and/or silk screening are applied on PCB underneath the connectorverify the thickness, or it could push up the connector bottom
- and may cause soldering defect and/or insufficient fillet formation.

 Prevent warpage of PCB, where possible, since it can cause soldering failure ;even with 0.1 mm max coplanarity.
- When mounting on the flexible board, please make sure to put a stiffener on the backside of the flexible board.
- We recommend a glass epoxy material with the thickness of 0.3 mm min.
- Do not add 1.0 N or greater external force when unreel or pick and place the connector etc. or it may get broken.
- Apply reflow temperature profile within the specified conditions.
 For specific applicantions, the recommended temperature may vary depending on type/volume/thickness of solder paste and size/thickness of PCB. Pleases Consult with your solder paste and equipment manufacturer for specific recommendations. The temperatures mentioned below refer to the PCB surface temperature near the connector contact leads.
 - Reflow method: IR reflow
- Number of reflow cycles:2 cycles MAX.



Time (Sec.)

| Instructions for PCB handling after mounting the connector |


Follow the instructions shown below when mounting on the PCB

[Caution]

- ·Splitting a large PCB into several pieces
- ·Installing mounting screw on PCB
- During the assembly processes decribed above, care shall be taken so as not to give any stresses of deflection or twisting to the PCB.
- Stresses applied on PCB may damage the connector as well.

 -The warpage of a 100 mm wide PCB should remain within 1.0 mm.
- The warpage of PCB may apply excessive stress on the connector and damage the connector(Example 27).

Example 27)



[Instructions on manual soldering]

instructions shown below when soldering the connector manually during repair work, etc.

- Do not perform manual soldering with the FPC inserted into the connector.

 Do not heat the connector excessively. Be very careful not to let the soldering iron touch any parts other than connector leads. Otherwise, the connector may be deformed or melt.

 Do not supply excessive solder (or flux).

 If excessive solder (on flux) is supplied on the contact loads, colder on flux may adhere.
- If excessive solder (or flux) is supplied on the contact leads, solder or flux may adhere to the contacts, resulting in poor conduction.
- Supplying excessive solder to the metal fittings may hinder locking lever rotation. resulting in breakage of the connector.

[Other]

– Attachment of foreign particles with the connector contact may lead to conduction failure. In this particular case, the conduction failure may be fixed by re-inserting the FPC.

<Instruction manual(4)>|

D

E

DRAWING EDC-388109-99-00 FH63S-**S-0.5SH(99) CL580 <u>8</u>/8

FORM HC0011-5-8 1