

This connector requires delicate and careful handling. Read through the instructions shown below and handle the connector properly. Each values indicating here are for reference and may differ from standard value.

INSTRUCTIONS FOR MOUNTING ON THE BOARD!

♦ Warp of Board

Minimize warp of the Board as much as possible. Lead co-planarity including reinforced metal fittings is 0.1 mm or less. Too much warp of the Board may result in a soldering failure.

♦Load to Connector

Do not add 1N or greater external force when unreel or pick and place the connector etc. or it may get broken.

In addition do not insert the FPC or operate the connector before mounting it.

♦ Lord to Board


- ·Splitting a large Board into several pieces
- ·Screwing the Board


Avoid the handling described above so that no force is exerted on the Board during the assembly process. Otherwise, the connector may become defective.

♦ Amount of Warp

The warp of a 100mm wide Board should be 1 mm or less.

The warp of Board suffers stress on connector and the connector may become defective.







INSTRUCTIONS ON INSERTING FPC AND CONNECTION!


♦ Use of the Actuator

- 1. Be very careful not to apply excessive force when releasing the actuator in the initial position.
 - If you use your nail or finger as shown below, the terminals may be deformed.





- otates around the rotational axis as shown below.
- actuator will not open more than 115°. Do not apply any force backward beyond this point. Otherwise, the actuator may come off or break.





- 4. Move the actuator at approximately the center.
- 5. Do not pinch or pick the actuator to lift it as shown below. Otherwise, it may break. (Do not carry out any operation other than rotating the actuator as shown in 2 above.)






<INSTRUCTION MANUAL(1)>


]	K 5	DRAWING NO.	EDC3-351252-01	
		PART NO.	FH55-22S-0.5SH	
		CODE NO.	CL580-3707-7-00	4/5


FORM HC0011-5-8 1

♦ Direction of Contacts This connector has contacts on the bottom. Thus, insert FPC with the exposed conductors face down.

- ♦ Inserting the FPC
 - 1. Insert the FPC by about 12 degrees along the surface and at a right angle to the connector. Insert it properly to the very end.










Right angle to the connector

- 2. Do not insert the FPC diagonally from above. If the FPC is inserted at a slant (incorrectly) as shown below in the FPC insertion process, the edge of the FPC may catch in the terminals, resulting in deformation of the terminals.




3. Do not rotate the actuator when FPC TAB is on right and left guides for positioning FPC. Make sure the position of FPC TAB and guides before rotate the actuator.





When FPC TAB is on right and left guides for positioning FPC, it causes the loase connection.



When FPC TAB is on right or left guide for positioning FPC, it causes the loose connection.

♦ Checking the Locking Condition

In the locked condition, make sure that the actuator is horizontal on the Board surface. Do not apply excessive force to it near the 0° position of the actuator. Otherwise, the terminals may be deformed.


[INSTRUCTIONS ON FPC LAYOUT AFTER CONNECTION]

♦ Load to FPC


Be very careful not to apply any force to the connector directly after inserting FPC. Otherwise, the connector may become unlocked or the FPC may break. In particular, design the FPC layout with care not to bend it sharply upward in a vertial direction near the insertion opening.

Fix the FPC when loads are applied to it continuously.

Load: 0.05Xn N MAX



- Move the actuator at approximately the center.
- ♦ Release the actuator to remove the FPC. Remove the FPC by about 12 degrees along the surface.



[OTHER INSTRUCTIONS]

♦ Instructions on Manual Soldering

Follow the instructions shown below when soldering the connector manually during repair work, etc.

- 1. Do not perform reflow soldering or manual soldering with the FPC inserted into the connector.
- 2. Do not heat the connector excessively. Be very careful not to let the soldering iron contact any parts other than connector leads. Otherwise, the connector may be deformed or melt.
- 3. Do not use excessive solder (or flux). If excessive solder (or flux) is used on the terminals, solder or flux may adhere to the contacts or rotating parts of the actuator, resulting in poor contact or a rotation failure of the actuator. Supplying excessive solder to the reinforcing bracket may hinder actuator rotation. resulting in breakage of the connector.

<INSTRUCTION MANUAL(2)>

111011100	1 1 0 11 111	MITONE (E)	
	DRAWING NO.	EDC3-351252-01	
HR5	PART NO.	FH55-22S-0.5SH	
	CODE NO.	CL580-3707-7-00	5

FORM HC0011-5-8