TO R

| COUNT | DESCRIPTION (| OF REVISION | NS | BA | СНКО | DAIL | | COUNI | | DESCRIPTION OF | MEN 12 IUNS | Вĭ | unv | DATI | ۵. |
|---|--|--|---|---------------|-------------|------------|-------------------|------------------------------|--|--|-----------------|---------|-----------|----------------|--|
| | | | | | | | | 4 | | | | | | | |
| | | | | | - | | | | | | | | | | |
| APPLICABLE | CTANDARD | | | | | | | | | | | • | | | |
| | | | |)E (| о то | , OE | or let | ODACE | | | _25 | °C T | n 4 | -85 °C | |
| OPERAT ING | | | -25 °C TO +85 °C STORAGE | | | | | | | WC | -25 | U II | ' | 55 0 | |
| RATING TEMPERATURE RANGE | | | TEMPERATU | | | | | | KE K | WGE | | | | | |
| VOLTAGE | | | AC 30 V , DC 42 V | | | | | | _ | | | | | _ | |
| CURRE | NT | | 2 A APPLICABLE | | | | | | E CAE | 3LE | | | | | |
| | | <u> </u> | | | SI | PECI | FIC | ATIO | ONS | | | | | | |
| IT | TEM | | | TF | ST ME | | | | | | QUIREMENTS | | | QT | AT |
| | RUCTION | | | - 11 | .01 ML | II KOD | | | | | | | | | |
| | | | 41E EV | 15.40 | 151110 | INCTO BE | `\IT | | TAGOO | ODING TO DOM | WILL. | | | \top | $\overline{}$ |
| GENERAL EXAM | | VISUALLY | | | UKING | INSTRUME | :NI. | | ACC | ording to Drai | MING. | | | 0 | Ŏ |
| MARKING | | CONFIRMED | | | | | | | | | | | | 0 | 0 |
| ELECT | RIC CHA | ARACT | ERI | ST | ICS | 3 | | | | _ | | | | | , |
| CONTACT RESISTANCE | | CONTACT SHALL BE MEASURED AT DC 1 A | | | | | | | | 15 mΩ MAX. | | | | 0 | 0 |
| | | CONTACT S | | | | | | A | " | mΩ MAX | | | | — | _ |
| INSULATION F | | | OO V DC | | | | | | 1 | 1000 MΩ MII | NI. | | | 0 | 0 |
| | | | | | | | | | 110.7 | | | | | | |
| VOLTAGE PROC | | | 00 V AC | | | | | | NO 1 | LASHOVER OR | BREAKDUMN. | | | 0 | 0 |
| MECHAN | VICAL C | <u> CHARA</u> | CTE | RI | STI | CS | | | | | | | | | |
| CONNTACT INSERTION AND \$\dip 0.53 | | | =0, 003 BY STEEL GAUGE. | | | | | | INS | ertion and Wi | THDRAWAL FOR | CES : | | 0 | - |
| WITHDRAWAL FORCES | | | | | | | | | 0. 18 | 5 N MIN. | | | | | |
| CONNECTOR INSERTION AND MEASURE | | | | | | | | | INS | ERTION AND WI | THORAWAL FOR | OFS : | | 0 | _ |
| | | | | | | | | | | N MAX. | IIDIUWE IGI | | | ~ | |
| | | | HOUT LOCKING DEVICE. OOD TIMES INSERTIONS AND EXTRACTIONS. | | | | | | | NTACT RESISTA | MOE: 20 | IAV | | + | |
| MECHANICAL (| UPERATION | 1000 11 | IMES IN | SEKII | UNS A | ND EXIKAL | iliuns. | | | | | | ••• | | ├ ─ |
| | | | | | | | | | | - RESISTAN | | | | | \vdash |
| VIBRATION | | FREQUENCY | Y: 10 - | → 55 | → 10 | (Hz) (10 | YC, 5mir | n), | (I)N | DELECTRICAL | Discontinuit | Y 0F 1 | 0 μs. | | - |
| | ls ls | | SINGLE AMPLITUDE 0.75 mm, AT 10 CYC, | | | | | | | DAMAGE, CRA | CK AND LOOSE | NESS, | 0F | | |
| | | FOR 3 DIR | RECTION | S. | | | | | PAR | TS. | | | | | |
| SHOOK | | | | | | | | | (TNr | ELECTRICAL DI | SCONT INUITY OF | 10 us | | 0 | <u> </u> |
| SHOOK | | FOR 3 TIME | | | | | | | 1 - | DAMAGE, CRACK | | • | | " | |
| | | | | | | | | | +- | | | u in | 110. | | ┼ |
| Breaking Stre | | MAX 100 N | | | | | UP AND | DOWN, | NO E | Reakage Max 10 | UN. | | | 0 | - |
| | | left and r | | | | | | | | | | | | | <u> </u> |
| ENVIR | ONMENT | AL CH | IARA | <u>CT</u> | ER | ISTIC | <u>cs</u> | | | 1.0 | | | | | , |
| DAMP HEAT | | exposed at | Г 40 °С, | 90 T | 95 % | , 96 h. | | | (I) | ASULATION RESIS | TANCE: 10 MΩ | MIN (AT | HIGH | | - |
| (STEADY STATE) | | | | | | | | | HUMI | DITY). | | | | | |
| | | | | | | | | (2)IN | ②INSULATION RESISTANCE: 100 MΩ MIN (AT DRY). | | | | | | |
| | | | | | | | | | (3)N |) DAMAGE, CRACK | AND LOOSENESS | OF PA | rts. | | |
| RAPID CHANGE OF | | TEMPERATURE $-55 \rightarrow R/T^{(1)} \rightarrow +85 \rightarrow R/T ^{\circ}C$ | | | | | | | 101 | NSULATION RES | ISTANCE: 100 | MO N | AIN. | 10 | 1 – |
| TEMPERATURE | | TIME 30 \rightarrow 2 TO 3 \rightarrow 30 \rightarrow 2 TO 3 min UNDER 5 CYCLES. | | | | | | | | | | | | | |
| | | | | | | | | | ②NO DAMAGE, CRACK AND LOOSENESS OF PARTS. | | | | | | |
| | | 1 | | | | | | | | | | | | _ | ┼ |
| CORROSION S | ALT MIST | EXPOSED (| | | | K SPKAT I | -UK 48 | <u>n</u> | \rightarrow | HEAVY CORROSI | | | | 10 | \vdash |
| DRY HEAT | | EXPOSED A | | | | | | | | DAMAGE, CRACK | | | | | <u> =</u> |
| COLD | • | EXPOSED A | AT -55 | °C, | 96 h. | | | | NO I | Damage, Crack | (AND LOOSENE | SS OF | PARTS. | . 0 | - |
| RESISTANCE | TO SOLDERING | SOLDER TE | EMPERAT | URE. | +350= | ±10°C. F | OR IMME | RSION | NO | DEFORMATION (| F CASE OF E | (CESSI) | /E | 0 | |
| HEAT | | DURATION, | | | | | | | 1500 | SENESS OF TH | Æ TERMINALS. | | | | 1 |
| SOLDERABILI | | SOLDERED | · | | TEMPER | ATIEDE 1 | 250+10 | °C F∩D | | DER SURFACE 1 | | OM PI | N-HOLE | . 0 | 1= |
| SOLDEWBILL | 11 | | | | | - | 300±10 | CIGN | • | WETTING AND C | | | 1 INCLE | · ~ | |
| | | IMMERSION | | | | | | | | | | | 0700 | _ | +- |
| | | ifxposed a | AT A DE | PTH · | | m FOR 4 | | | | WATER PENETRA | | | CHOK. | <u> </u> | ↓ _ |
| SEALING | | | | | | | | | | | INDIONE COMMITT | | | - 10 | 0 |
| SEALING AIR TIGHTNE | SS | APPLY AIR | | URE | 17. 6kP | a FOR 0. | omin il | INSID | E NO | AIR BUBBLES | INDIDE CONNEC | CTOR. | | | |
| | SS | | r press | URE. | 17. 6kP | 'a FOR 0. | 5min il | INSIDI | E NO | AIR BUBBLES | INSTILE CONNEC | CTOR. | | | |
| AIR TIGHTNE | | APPLY A !F | r press | SURE | 17. 6kP | 'a FOR 0.: | 5min IC | DRAWN | <u></u> | DESIGNED | CHECKED | | ROVED | RELE | ASED |
| AIR TIGHTNE | | APPLY A !F | r press | TURE | 17. 6kP | a FOR 0.: | T | DRAWN | <u> </u> | DESTGNED | CHECKED | APP | | | ASED |
| AIR TIGHTNE | | APPLY A !F | r press | SURE | 17. 6kP | 'a FOR 0.: | T | DRAWN | <u> </u> | DESTGNED | CHECKED | APP | | | ASED |
| | | APPLY A !F | r press | SURE | 17. 6kP | 'a FOR 0.∶ | T | DRAWN | <u> </u> | DESTGNED | CHECKED | APP | | | ASED |
| AIR TIGHTNE REMARI | KS | APPLY ATE | r press | SURE | 17. 6kP | 'a FOR 0.∍ | T | DRAWN | <u> </u> | DESTGNED | CHECKED | APP | | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T | KS : Room tempe | APPLY AIF CONNECTOF | r Press r. | | | aFOR 0.∍ | T | DRAWN | <u> </u> | DESTGNED | CHECKED | APP | | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T Unless othe | KS : ROOM TEMPE erwise specifi | APPLY AIR CONNECTOR RATURE ed, refer | R PRESS R. | S C E | | | H '(| DRAWN .Kawash 04.5 | <u> </u> | | CHECKED | APP | | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T Unless othe | KS : Room tempe | APPLY AIR CONNECTOR RATURE ed, refer | R PRESS R. | S C E | | | H '(| DRAWN .Kawash 04.5 | <u> </u> | DESIGNED H. Zemba '04.05.28 | CHECKED | APP | | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T Unless othe | KS : ROOM TEMPE erwise specifi alification To | APPLY AIR CONNECTOR RATURE ed, refer est AT:As | R PRESS R. to JI: | S C 5 | | | H '(| DRAWN .Kawash 04.5 | <u> </u> | DESTGNED | CHECKED M.Sato | M.C. | 25.3 | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T Unless othe | KS : ROOM TEMPE erwise specifi | APPLY AIR CONNECTOR RATURE ed, refer est AT:As | R PRESS R. to JI: | S C 5 | | | H , ole Tes | DRAW .Kawash 04.5 | N nima +22 | DESIGNED H. Zemba Oq.ot.28 PART NO. | CHECKED M.Sato | APP | 25.3 | | ASED |
| AIR TIGHTNE REMARI NOTE(1) R/T Unless othe | KS: ROOM TEMPE rwise specifi alification To | APPLY AIR CONNECTOR RATURE ed, refer est AT:As | R PRESS R. to JI: | S C 5 æ Te | | :Applicat | H , ole Tes | DRAWN Kawash 04.5 t | N nima +22 | DESIGNED H. Zemba O9.05.28 PART NO. | CHECKED M.Sato | M.C. | 25.3 | | ASED |