<u>1. Scope</u>

This document specifies the cable assembly procedures of crimping the crimp contact to the cable (AWG#26 to 34) and inserting the contact to the crimp socket for DF57 Series.

2. Part Number 2

Part No.	Description	
DF57-%SCF(##)	Crimp contact	
DF57-%SCFA(##)		
DF57H-*S-1.2C(##)	Crimp socket	
DF57AH-*S-1.2C(##)		

*: Number of position(##): Peculiar specification number%:Applicable wire size

3. Cable Assembly Procedure

3.1. Cable Stripping

Follow the Crimping Quality Standard (ATAD-H0404), and srip the cable jacket. Make sure that there is no damage on the center conductor of the cable.

3.2. Crimping Process

Crimp the contact by using the applicator(AP105-DF57-2628S,AP105-DF57-2830S, AP105-DF57-3234S,AP105-DF57-2830SA). Confirm that the crimp height and configuration meet the crimp condition and Crimping Quality Standard (ATAD-H0404).

3.3. Crimped Contact Insertion to Crimp Socket

Hold the cable of crimped contact and insert to each contact cavity of the crimp socket. (Insertion direction is as shown below.)





