
Procedures for using the Crimp Terminal Extracting Tool

Extracting Tool Name	DF-C-PO(C)
Applicable Crimp Terminals	■DF1B-****PC(F)(B) ■DF1-PD2428SC(F)B ■DF1B-**PR(F)

■Procedures (e. g.) DF1B-*EP-2.5RC, DF1B-2428PCF

1. Insert the extraction tool from the mating side into the gap between the housing and the terminal on both sides.
2. When the extraction tool is completely inserted, the terminal lance is lowered.
3. Pull the wire to pull out the terminal with the extraction tool inserted.



Case cross-section

Feb.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.

	COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
△1	0				

TITLE DF-C-PO(C) Procedures for Using the Crimp Terminal Extracting Tool	HIROSE ELECTRIC CO., LTD.		
	APPROVED	SJ. OKAMURA	20210413
	CHECKED	SZ. ONO	20210413
	DESIGNED	SN. MIWA	20210413
	WRITTEN	KT. NUMATA	20210413
TECHICAL SPECIFICATION	ETAD-H1020-00	△1	1 / 1

FORM HC0011-9-1