Apr.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



【 PRECAUTIONS FOR HANDLING 】

◆Connector insertion and extraction

a. Connector shall be extracted vertically by specialised extraction JIG.
Part No. : D. FL75-LP-N
Never hold the cable when extracting the cable because it damages the connector.

b. Insert the connector as perpendicularly to the mating surface as possible by aligning the mating axes of both connectors. Do not excessively slant the connectors when inserting.

◆ Allowable loads on the cable after the connectors are mated.
The left figure below show the maximum allowable loadson the cable. Do not apply loads exceeding these values to the cable.

△1◆ Please don't apply the power of the direction which lifts a cable. There is a danger that the inserted-in plug will Separate.
When you perform wiring which curves a cable as shown in the middle figure below, please be careful.

◆ In the case of short products (100mm or less) or when the cable is bent during routing, it is recommended to press a cushioning medium (10N or less) on the back of the plug after mating in order to avoid the risk of characteristic fluctuation or separate of the mating.

【 DIMENSIONS OF CONNECTOR 】







HALOGEN FREE

NO.	PART NO.	CODE NO.	NO.	PART NO.
1	D. FL75-LP(P)-084	CL331-0078-0-00	2	1.5Dia coaxical cable (Green)

UNITS	SCALE		COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
mm	FREE	△1	1	DIS-D-00010155	YK. KIUCHI	MT. KANEKO	20220112

HIROSE ELECTRIC CO., LTD.

APPROVED	NK. NINOMIYA	20190808
CHECKED	NK. NINOMIYA	20190808
DESIGNED	YK. KIUCHI	20190808
DRAWN	YK. KIUCHI	20190808

DRAWING NO.	EDC-384291-18-00
PART NO.	DFL75-2LPP-084N9D-A-200
CODE NO.	CL0321-0943-0-18 △1 1/1

FORM HC0011-5-51

HRS DRAWING FOR REFERENCE