



FORM HC0011-5-8 1

①By positioning the convexity of the socket sides ②Slightly press the socket down at cable side ③Press down at the lever side with stabilizing to the header concavity, align the centers of the to tilted angle. the cable side to insert. Mating completes. socket and the header in pitch direftion. Socket HRS DRAWING FOR REFERENCES Pitch direction D ⊕Hook the lever with finger nail. ③Lift up to the upper direction and positive lock is released. Removal completes. EDC-343908-21-01

HS.

DF57H-6P-1.2V(21)

CL666-0108-8-21