

Precoutions ◆Notification for Insertion Extraction

1) Please insert(extract) the crimping socket straight to the mating connector. Insertion(extraction) at tilted angles applies load concentration to the connetor end and may cause deformation (at connection area, socket and header case, etc). There is firing risk using this kind of defomed connector.

 \triangle

Insertion(Extraction) Insert/Extract vertically Insertion Extraction

Of Sextraction

When it is hard to extract, please lightly insert the connector beforehand and then pull it with releasing the lock.

Forced extraction has a risk of connector breakage.

Otification of wiring


When using a thick cable, short cable length and bending class the please note that there is firing risk using definition of the pullipse of the lock.


◆Notification of wiring



FORM HC0011-5-8 1

1) When using a thick cable, short cable length and bending close to the connector end, these load concentration may couse deformation. Please note that there is firing risk using deformed connector.





ĸ	DRAWING NO.	EDC-390347-00-00
	PART NO.	DF22B/C-1RS/P-7.92
	CODE NO.	CL0680-1214-0-00 🛕 3