

Note 1. Use in combination with a suitable counterpart.
When combined with an incompatible plug, there might be damage on product-function and the product it self.
If the inappropriate counterpart is assembled, it might cause disfunction and damage on product.


2. POK15-P-15D PART LIST

	Product Name : POK15-P-15D SLEEVE(800) Product CODE : CL 6341-0011-7-800
	Product Name : POK15-P-15D M/C(800) Product CODE : CL 6341-0010-4-800
	Product Name : POK15-P-15D PLUG(800) Product CODE : CL 6341-0008-2-800

[Reference]Connecting Drawing (Scale 3:1)

3	Be-COPPER	Ni PLATING	4	COPPER	Ni PLATING		
1	COPPER	Ni PLATING	2	PBT	COLOR: GRAY		
NO.	MATERIAL	FINISH . REMARKS		NO.	MATERIAL	FINISH . REMARKS	
CODE NO. (OLD)			DRAWN	DESIGNED	CHECKED	APPROVED	RELEASED
			D.G KIM 19.06.19	D.G KIM 19.06.19	H.S KIM 19.06.19	H.S KIM 19.06.19	<div><div>ENG</div><div>19.06.19</div><div>DEPT</div></div>
		DRAWING NO. EDC4-611539		PART NO. P0K15-P-1.5D PLUG(800)			
SCALE 5:1							
UNITS mm		HIROSE KOREA CO.,LTD.		CODE NO. CL 6341-0008-2-800			1/2


[Caution]



* This product should be fixed with fixture so that it does not rotate vertically and horizontally when it is combined with mating material.


The product must be assembled with counterpart and fixed by it's tool to prevent it from rotating (If it is not fixed by the tool, it might cause disfunction in usage)

[Example of incident (when there is no tool for fixation)]





* If you use this product without the fixing structure, it may cause loss of function of the product, disconnection of the connection part, peeling of the counterpart due to rotation of up and down and left and right.

If the product is used without fixation, it might(rotation) cause disfunction, disconnection of wire, PCB peeling off.



* If you use this product without the fixing structure, If the force acts in the direction differently from the center of the product, it may cause the loss of function due to eccentricity of the product.

If the product is used without fixation and force is applied in different direction from the center of the product, it may cause disfunction due to eccentricity of the product.

	DRAWING NO. EDC4-611539	PART NO. POK15-P-1.5D PLUG(800)	<div>2/2</div>
SCALE 5:1	 HIROSE KOREA CO.,LTD.	CODE NO. CL 6341-0008-2-800	
UNITS mm			