



適 用 規 格					
定 格	使用温度範囲	-35℃～ +85℃ (注1)	保存温度範囲	-10℃～ +60℃ (注3)	
	使用湿度範囲	40% ～ 80% (注2)	保存湿度範囲	40% ～ 70% (注3)	
	電 圧	250V AC/DC	適合電線	UL1061, UL1007 AWG20～22	
	電 流	AWG20 : 5A/pin AWG22 : 3A/pin	適合コネクタ	DF1BA-*(D) EP-2. 5RC DF1B-*(D) EP-2. 5RC	
性 能					
	項 目	試 験 方 法	規 格	QT	AT
構 造	外観, 構造, 仕上げ	目視, 寸法測定器にて測定する。	図面と合致していること。	○	○
	表示	目視にて確認する。		○	○
電 氣 的 性 能	接触抵抗	100mA (DC又は 1000 Hz) で測定する。	30 mΩ 以下	○	—
機 械 的 性 能	繰り返し動作	30 回の抜き差しを行う。	①接触抵抗: 30 mΩ 以下 ②破損、ひび、部品のゆるみがないこと。	○	—
	耐振性	周波数 10～55 Hz、片振幅 0.75 mmで 3 方向 各 2 時間サイクル試験する。	①1μs以上の電氣的瞬断がないこと。 ②破損、ひび、部品のゆるみがないこと。	○	—
	耐衝撃性	加速度 490 m/s ² 、持続時間 11 ms、 正弦半波 3 軸両方向 各 3 回試験する。	①1μs以上の電氣的瞬断がないこと。 ②破損、ひび、部品のゆるみがないこと。	○	—
環 境 的 性 能	定常状態の耐湿性	温度 +40 ± 2℃、湿度 90～95 %中に 96 時間放置する。	①接触抵抗: 30 mΩ 以下 ②破損、ひび、部品のゆるみがないこと。	○	—
	温度サイクル	温度 -55 → 5～35 → 85 → 5～35℃ 時間 30 → 5～10 → 30 → 5～10分 を 5 サイクル 試験する。	①接触抵抗: 30 mΩ 以下 ②破損、ひび、部品のゆるみがないこと。	○	—
備考					
(注1) 通電時の温度上昇を含む。					
(注2) 結露のないこと。					
(注3) 未使用品の梱包状態に適用。 					