

1<sup>st</sup> September 2022

HIROSE ELECTRIC CO., LTD.

Impact on our products by Inappropriate Identification on  
Nylon resin Amilan and PBT resin TORAYCON of Toray Industries, Inc.

Toray Industries, Inc. (Hereinafter Toray) announced followings about Nylon resin Amilan and PBT resin TORAYCON (Hereafter Applicable materials) that were improperly identified as receiving certification from Underwriters Laboratories, a third-party safety science organization in the United States (hereinafter, "UL").

We are writing to inform you of the impact on our products.

1 Announcement from Toray

As a result of discussions between UL and Toray regarding the handling of UL certified applicable materials, Toray received the following conclusion from UL.

- (1) For all applicable materials for which inappropriate actions were made in FUS (follow-up service) in the past, it has been decided that the existing UL certification registration continues as it is.
- (2) Even for grades for which inappropriate actions were not made, UL certification registration continues as it is.

2 Impact on our products

From the announcement from Toray that the UL certification registration of the applicable materials continues, there is no impact on UL certification registration of our products using the applicable materials.

We continue to supply our products using the applicable materials.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are appreciated.