


Apr.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

△ 【 ASSEMBLE TOOL 】


- ①Jig for soldering outer conductor: SMP-J/SO-MD1
②Jig for soldering center conductor: SMP-J/SO-MD2
③Attachment for inspection of dimension for mating area: SMP-J/IN-MD
④Base for inspection of dimension for mating area: SMP/IN-MD-BASE



△ 【 USAGE PRECAUTIONS 】

1. Please insert or extract a SMP jack as perpendicularly as possible to a receptacle. If aligned insertion or extraction is not performed, it could damage or deform an outer conductor part of the jack.
Recommend using an extraction jig for the jack

- 2 Semi-flexible cable is made solder connection with a connector. If excess load on the soldered section is applied, it could damage or deform the section.
Please handle it with care.



2	PTFE		4	BRASS	GOLD PLATING
1	BERYLIUM COPPER	GOLD PLATING	3	BERYLIUM COPPER	GOLD PLATING
NO.	MATERIAL	FINISH . REMARKS	NO.	MATERIAL	FINISH . REMARKS
UNITS mm		SCALE 10: 1	COUNT △ 1	DESCRIPTION OF REVISIONS DIS-D-00005251	DESIGNED TM. YOSHIDA
HIROSE ELECTRIC CO., LTD.		APPROVED : TO. KATAYAMA	20171101	DRAWING NO. EDC-373427-00-00	DATE 20200918
		CHECKED : KY. SHIMIZU	20171101	PART NO. SMP-J-SF085	
		DESIGNED : TM. YOSHIDA	20171101	CODE NO. CL338-1100-0-00	△ 1/1
		DRAWN : TM. YOSHIDA	20171101		