APPLICA	BLE STAND	ARD							
RATING	OPERATING TEMPERATURE RANGE		-40 °C TO 105	5 °C (NOTE1)	STORAGE TEMPERA CURREN	TURE RANGE	NGE -40 °C TO 10		
VOLTAGE			250 V A	1 A					
			SPE	CIFICAT	IONS				
	ITEM		TEST METHO	D		REQU	JIREMENTS	QT	AT
CONSTR	UCTION	· ·							
GENERAL EXAMINATION		VISUALLY	VISUALLY AND BY MEASURING INSTRUMENT.			DING TO DRAV	VING.	×	×
MARKING		CONFIRM	IED VISUALLY.					×	×
ELECTRI	C CHARACTE	RISTICS	RISTICS						
CONTACT F	RESISTANCE	1A DC.			SIGNAL	SIGNAL : $30 \text{ m}\Omega$ MAX, SHIELD : $60 \text{ m}\Omega$ MAX.			_
	CONTACT RESISTANCE MILLIVOLT LEVEL METHOD		20 mV AC MAX, 0.1 mA(DC OR 1000Hz)			SIGNAL: $30 \text{ m}\Omega$ MAX, SHIELD: $60 \text{ m}\Omega$ MAX.			_
					100 MO	MINI		×	
	VOLTAGE PROOF		650 V AC FOR 1 min.			100 MΩ MIN. NO FLASHOVER OR BREAKDOWN.			+=
	ICAL CHARAC				110121	SHOVER OR B	INE/INDOVIN.	×	
	AL OPERATION		INSERTIONS AND EXT	TRACTIONS	① CON	TACT RESISTA	VICE :	×	1 _
WESTIANIOAL OF ERATION		TIMES INSERTIONS AND EXTRACTIONS.			_	SIGNAL: $60 \text{ m}\Omega$ MAX, SHIELD: $120 \text{ m}\Omega$ MAX.			
					2 NO E	AMAGE, CRACI	K AND LOOSENESS OF PARTS.	×	_
VIBRATION		FREQUENCY 20 TO 200 Hz,			_	① NO ELECTRICAL DISCONTINUITY OF 10 μs.			_
		43.1 m/s ² AT 3 h FOR 3 DIRECTIONS.			-	② CONTACT RESISTANCE: SIGNAL: 60 mΩ MAX. SHIELD: 120 mΩ MAX.			-
							, -	×	_
SHOCK		FREQUENCY 20 TO 50 Hz.			_	(3) NO DAMAGE, CRACK AND LOOSENESS OF PARTS. (1) NO ELECTRICAL DISCONTINUITY OF 10 µs.			
		66.6 m/s ² AT 1 h.			_	② CONTACT RESISTANCE :			_
							MAX, SHIELD: $120 \text{ m}\Omega$ MAX.		
						③ NO DAMAGE, CRACK AND LOOSENESS OF PARTS.			_
LOCK STRE	NGTH	APPLYING A PULL FORCE THE MATING AXIALLY AT 78.4N MAX.			_	① DURING APPLYING,MATING COMPLETELY. ② AFTER APPLYING,NO DEFECT OF MATING PARTS.			
END/IDON	INAENITAL OLL				Ø AFTE	R APPLYING,N	DEFECT OF MATING PARTS.	×	
	IMENTAL CHA				Ø 001	TA OT DEGICE	Non	×	Т
DAMP HEAT (STEADY STATE)		EXPOSED AT 60 °C, 90 ~ 95 %, 500 h.			_	① CONTACT RESISTANCE : SIGNAL : $60 \text{ m}\Omega$ MAX, SHIELD : $120 \text{ m}\Omega$ MAX.			_
(STEADT S	IAIL)						STANCE: 100 M Ω MIN.	×	_
					3 NO E	AMAGE, CRACI	AND LOOSENESS OF PARTS.	×	-
RAPID CHANGE OF		TEMPERATURE-40→5 TO 35→ 85→5 TO 35°C			•	① CONTACT RESISTANCE :			_
TEMPERATURE		TIME $30 \rightarrow 5 \rightarrow 30 \rightarrow 5 \text{ min}$					MAX, SHIELD: 120 mΩ MAX.	×	
		UNDER 1000 CYCLES.				 INSULATION RESISTANCE: 100 MΩ MIN. NO DAMAGE, CRACK AND LOOSENESS OF PARTS. 			_
DRY HEAT		EXPOSED AT 105°C, 300 h.			_	① CONTACT RESISTANCE :			
DICT FILM		EXT 6625 X1 100 0, 000 11.			SIGI	SIGNAL: $60 \text{ m}\Omega$ MAX, SHIELD: $120 \text{ m}\Omega$ MAX.			
					② NO E	② NO DAMAGE, CRACK AND LOOSENESS OF PARTS.			_
COLD		EXPOSED AT -55°C, 120 h.			_	① CONTACT RESISTANCE :			-
					_	SIGNAL : $60 \text{ m}\Omega$ MAX, SHIELD : $120 \text{ m}\Omega$ MAX. ② NO DAMAGE, CRACK AND LOOSENESS OF PARTS.			
RESISTANCE TO SO ₂ GAS		EXPOSED IN 500 PPM FOR 8 h.				CONTACT RESISTANCE :			 -
1120101711102 10 002 0710						SIGNAL : $60 \text{ m}\Omega$ MAX, SHIELD : $120 \text{ m}\Omega$ MAX.			
RESISTANCE TO		SOLDER TEMPERATURE, 260°C			NO DEF	NO DEFORMATION OF CASE OF EXCESSIVE			-
SOLDERING HEAT		REFLOW 2 TIMES.			LOOSE	NESS OF THE	ΓERMINALS.		
									1
						ı		1	<u> </u>
COUN	NT DE	SCRIPTION	N OF REVISIONS		DESIGNED)	CHECKED	DA	TE
<u>/</u> 0\							1		
REMARK	DE THE TEMPES **	בווחב טוסייים	JRE RISING BY CURRENT.			APPROVE	ED KI. HIROKAWA	2020	00331
" "INCLUI	DE THE TEMPERAT	UKE KISING				CHECKE	D EJ. WAKATSUKI	2020	00327
						DESIGNE	TS. KUBOTA	2020	0325
						DRAWN	YK. MITSUISHI	2020	00313
Note QT:Qualification Test AT:Assurance Test X:Applicable Test					DRAW	DRAWING NO. ELC-166942-5		57-00)
שנ	SF	PECIFICATION SHEET			PART NO	PART NO. GT17H-4P-2H (A) (57		7)	
KS	HIR	OSE ELE	OSE ELECTRIC CO., LTD.		CODE NO	. CL7	CL767-0170-6-57		