
Procedures for using the Crimp Terminal Extracting Tool						
Extracting Tool Name	DF-C-PO(C)					
	■DF1B-****PC(F)(B)					
Applicable Crimp Terminals	■DF1-PD2428SC(F)B					
	■DF1B-**PR(F)					

■ Procedures (e. g.) DF1B-*EP-2.5RC, DF1B-2428PCF

- 1. Insert the extraction tool from the mating side into the gap between the housing and the terminal on both sides.
- 2. When the extraction tool is completely inserted, the terminal lance is lowered.
- 3. Pull the wire to pull out the terminal with the extraction tool inserted.



	COUNT	OUNT DESCRIPTION OF REVISIONS DESIGNED)		CHECKED		DATE	
Δ	0								
TITLE					HIROSE ELECTRIC CO., LTD.				
DF-C-PO(C) Procedures for Using the Crimp Terminal Extracting Tool			APPROVED SJ. 01		SJ. OKAMURA	A	20210413		
			CHEC	ECKED SZ. ONO			20210413		
				DESIG	DESIGNED SN. MI			20210413	
				WRIT	TTEN KT. NUMATA			20210413	
TECHICAL SPECIFICATION				ETAD-H1020-00			Δ	1/1	