APPLICAB		DARD									
<u> </u>	PERATING EMPERATURE RANGE		-40°C TO + 85°C (NOTE 1) 1		STORAGE TEI RANGE		1PERATURE		-10°C TO + 60°C		
	OPERATING HUMIDITY RANGE		100/ TO 000/ (NOTE 0)		STORAG HUMIDIT	AGE DITY RANGE			40% TO + 70%		
V	VOLTAGE		250V AC		APPLICA	PLICABLE CONNECTOR		OR	DF11-*DS-2C		
С	CURRENT		0. 5A	APPLIC		CABLE CABLE			UL1061/UL1007	AWG30	
			SPEC	IFICA	OITA	VS.					
ITE	M		TEST METHOD					REQU	IREMENTS	QT	AT
CONSTRU	JCTION									•	•
GENERAL EXAMINATION		VISUALLY AND BY MEASURING INSTRUMENT.				ACCORDING TO DRAWING.					Х
MARKING		CONFIRMED VISUALLY.								X	X
ELECTRIC						00 0					
CONTACT RESISTANCE		100mA (DC OR 1000 Hz).				30mΩ MAX.					-
MECHANI	CAL CHA	RACTE	ERISTICS								
MECHANICAL OPERATION		50 TIMES INSERTIONS AND EXTRACTIONS.				① CONTACT RESISTANCE: 30mΩ MAX. ② NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				X	-
CONTACT INSERTION AND EXTRACTION FORCE		□0.5±0.002 BY STEEL GAUGE.				INSERTION FORCE 4.4N MAX EXTRACTION FORCE 0.3N MIN				Х	_
		FREQUENCY 10 TO 55 Hz, SINGLE AMPLITUDE 0.75 mm, AT 2 h, FOR 3 DIRECTIONS.				① NO ELECTRICAL DISCONTINUITY OF 1μs. ② NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				X	-
		490 m/s <sup>2</sup> DURATION OF PULSE 11 ms AT 3 TIMES FOR 3 DIRECTIONS.				① NO ELECTRICAL DISCONTINUITY OF 1μs. ② NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				Х	-
ENVIRONI	MENTAL	CHAR	ACTERISTICS		L						
TEMPERATURE I		TEMPERATURE -55→ 5 TO 35→ 85→ 5 TO 35 °C  TIME 30→10 TO 15→30→10 TO 15 min  UNDER 5 CYCLES.				① CONTACT RESISTANCE: 30mΩ MAX. ② NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				X	-
DAMP HEAT (STEADY STATE)		EXPOSED AT 40 ± 2 °C, 90 TO 95 %, 96 h.			1	<ol> <li>CONTACT RESISTANCE: 30mΩ MAX.</li> <li>NO DAMAGE, CRACK OR LOOSENESS OF PARTS.</li> </ol>				X	_
NOTE 2:NO CO	NDENSING.		E RISE BY CURRENT		DECION	JED			CHECKED		۸ΤΕ
<u> </u>			ON OF REVISIONS DESIG -H-008540 MI. SAK						CHECKED HK. UMEHARA		ATE 02, 26
Unless otherwise specifid ,			l l						TS. SAKATA	09. 11. 17	
	- 1	,					CHEC		TS. FUKUSHIMA		11. 17
							DESIG	NED	TH. YOSHIZAWA	09.	11.16
							DRA'	WN	TH. YOSHIZAWA	09.	11.16
Note QT:Qualification Test AT:Assurance Test X:Applicable Test					DR	RAWING NO.			ELC4-081092-01		
HRS	SF	SPECIFICATION SHEET			PART NO.		DF11-30SCFA (04)				
HIR		OSE ELECTRIC CO., LTD.			CODE NO.		CL543-0607-6-04			Λ	1/1